

SW-ID: 693903

## Relevant Device Types

- Positioner 8692
- Process-Controller 8693

Release Version	Release Date	Description	Added, Removed, Changed or Fixed
<b>2.00</b>	<b>July 19, 2022</b>	<i>Supported FW version B.11.00 and higher</i>	
		<i>Config assembly</i>	<b>Added</b>
		<i>zError</i>	<b>Added</b>
		<i>Change mapping of objects</i>	<b>Changed</b>
		<i>Object Route function is disabled by default</i>	<b>Changed</b>
		<i>Description of NamurStatus (reserved bits 4-7)</i>	<b>Fixed</b>
<b>1.05</b>	<b>Mar 12, 2021</b>	<i>Supported FW version B.05.01 and higher</i>	
		<i>Clean up files for positioner and process controller</i>	<b>Bugfix</b>
<b>1.04</b>	<b>Sept 18, 2018</b>	<i>Supported FW version B.05.01 and higher</i>	
		<i>IOC license added</i>	<b>Added</b>
		<i>Change order in assembly</i>	<b>Changed</b>
		<i>Correct datatype and bytelength of string parameters</i>	<b>Bugfix</b>
<b>1.03</b>	<b>July 26, 2018</b>	<i>Supported FW version B.02.01 to B.04.01</i>	
		<i>Byte length of startTune and z_OPmode was wrong</i>	<b>Changed</b>
<b>1.02</b>	<b>Feb 01, 2018</b>	<i>Supported FW version B.02.01 to B.04.01</i>	
		<i>Add Parameters to start Tunes from fieldbus</i> <i>-startTune</i> <i>-z_OPmode</i>	<b>Added</b>
<b>1.01</b>	<b>Dez 21, 2017</b>	<i>Supported FW version A.01 to B.02</i>	
		<i>first released version</i>	